Bell, Megan

From: Anderson, John D
Sent: Tuesday, September 1, 2026 4:59 PM
To: locations@flocksafety.com
Cc: Adams, Michael
Subject: Fw: [EXTERNAL] RELO-TN - Johnson City PD-P#0190 [redacted]-(9/1)

Hi,

I am following up on the below message from Kory. Deputy Chief Adams asked me to follow up and find a new location. I am recently hired to the PD here as the manager of the new Real Time Information Center, and am trying to help Deputy Chief Adams with the pending installs.

As I am coming in new to this, some of my following input/questions might have been addressed previously.

I do not know what an RLCC is or pull stations or what you mean by that sentence.

Your reference to the poles being flagged, do you mean the decorative flags on them or they are flagged by Brightridge? I found another pole, but it looks like all the others in that area. It is at [redacted] at the corner of the [redacted]. It likely will have the same issues, but we should be able to remove the flag on one of those poles. If this will still not work, I can find other proposed locations. Feel free to call me if easier to discuss on a call, my cell number is below.

JD Anderson
423-483-5864

From: Adams, Michael
Sent: Tuesday, September 1, 2026 1:44 PM
To: Anderson, John D
Subject: FW: [EXTERNAL] RELO-TN - Johnson City PD-P#0190 [redacted]-(9/1)

From: Location Support Team <locations@flocksafety.com>
Sent: Tuesday, September 1, 2026 12:27 PM
To: Adams, Michael <madams@johnsoncitytn.org>
Subject: [EXTERNAL] RELO-TN - Johnson City PD-P#0190 [redacted]-(9/1)

****CAUTION: External Email**** This email originated from outside of Johnson City's e-mail servers. DO NOT click links or open attachments unless you recognize the sender and know the content is safe.

Hi Captain Adams,

Kory here from the Location Support Team. I'm reaching out regarding location **P#0190 at** [redacted]

Work order **00997271** was scheduled for a site survey. Upon arrival, the technician found that the cables in the existing pole are dedicated to the signal lights and crosswalk controls. The nearest RLCC is more than 350 feet away, with six in-ground pull stations along the route, and no alternate location is currently available. Your Account Project Manager, Cali, reviewed the site and confirmed that a new location will need to be selected. There are decorative light poles in the area owned by Brightridge, but they are currently flagged and therefore do not appear to be viable options.
Please let me know how you would like to proceed.

Stay Safe,
Kory
Flock Location Support



thread::N4i1p-srJdS3cAm7fy6TIg4::