Bell, Megan

From: Location Support Team <locations@flocksafety.com>
Sent: Tuesday, September 1, 2026 12:27 PM
To: Adams, Michael
Subject: [EXTERNAL] RELO-TN - Johnson City PD-P#0190 [redacted]-(9/1)

CAUTION: External Email This email originated from outside of Johnson City's e-mail servers. DO NOT click links or open attachments unless you recognize the sender and know the content is safe.

Hi Captain Adams,

Kory here from the Location Support Team. I'm reaching out regarding location **P#0190 at** [redacted].

Work order **00997271** was scheduled for a site survey. Upon arrival, the technician found that the cables in the existing pole are dedicated to the signal lights and crosswalk controls. The nearest RLCC is more than 350 feet away, with six in-ground pull stations along the route, and no alternate location is currently available.

Your Account Project Manager, Cali, reviewed the site and confirmed that a new location will need to be selected. There are decorative light poles in the area owned by Brightridge, but they are currently flagged and therefore do not appear to be viable options.

Please let me know how you would like to proceed.

Stay Safe,
Kory
Flock Location Support



thread::N4i1p-srJdS3cAm7fy6TIg4::